SHEET INDEX No. DESCRIPTION TITLE SHEET SITE DEVELOPMENT PLAN SITE DEVELOPMENT PLAN GRADING AND SEDIMENT CONTROL PLAN NOTES AND DETAIL SHEET PROFILES AND DETAIL SHEET LANDSCAPE PLAN LANDSCAPE PLAN 10 EXISTING CONDITIONS PLAN EXISTING CONDITIONS PLAN

THE PAVEMENT DETAILS SHOWN ON THESE PLANS REFLECT THE HOSINARD COUNTY WINMAM STANDARD PAVEMENT SECTIONS AND ARE NOT SASED ON SITE SPECIFIC CONDITIONS. PRIOR TO PAVING, THE FINAL PAVEMENT SECTIONS SHALL BE DETERMINED BY A QUALIFIED GEOTECHNICAL GROWNER BASED ON IN-STU TESTING OF THE FINSHED SUBGRADE. ANY PAVEMENT SECTION DETERMINED BY THE GOTTECHNICAL ENGINEER THAT IS LESS THAN THE HOUMAD COUNTY MINIMAM STANDARD, SHALL FIRST SE APPROVED BY THE HOUMAD COUNTY DEPARTMENT OF PUBLIC WORKS. THE TESTING AND GEOTECHNICAL ENGINEER SHALL BE FURNISHED BY THE OWNER.

to the coordinated shown hereon are eased on had et, warrand coordinate

PERSON AS PROJECTED BY HOMPING COUNTY MONUMENT NO. SIEA AND COSE.

80. NO WETLANDS DUET ON PAPECEL A-E. BUISTING WETLANDS IN YICINITY OF FOND DO BUIST AND A FEBRUIT TO DISTURD THESE WETLANDS HAS BEEN GRANTED BY THE MARYLAND DEPARTMENT OF NATURAL RESOURCES ON MAY 18, 1808, WITH AUTHORIZATION NO.

90. TRAIFIC STUDY PREPARED BY THE TRAIFIC GROUP, INC. DATED DECEMBER 0, 1994

16. STORMHATER HAMASEMENT QUANTITY AND QUALITY CONTROL FOR THIS DEVELOPMENT IS PROVIDED BY A RETENTION FACILITY, AND WILL BE PROVIDELY MAINTANED BY OWNER.


22. WATER HETER IS TO SE LOCATED RISIDE THE SUILDING.

THEODER OF WALLDOOM SAM ON SAM ON 12

85 WATER AND SEWER SERVICE IS PRINATE.


SITE DEVELOPMENT PLAN SYSTEMS

4th ELECTION DISTRICT HOWARD COUNTY, MARYLAND



Existing zoning:	9-2				
FILE MAGNETS:	8A-93-31B F WP-94-24 8B 957H	-95-80			
AREA OF PARCEL:		197	, geb of	5.19 Ac	i.
PROPOSED USE:	OFFICE BUILDING				
BHILDING	NOURS OF	HAX. NO.	BUILDING		Parking Provided
EX. DAY CARE CENTER	6:30 AM-6:30 PM	ě.	3,000 1	6	6
EX. OFFICE	8:00 AM-5:00 PM	150	15,680	52	66
PROP. OFFICE	8:00 AM-5:00 PM	130	18,792	62	60
		-	5,440 * ATRIUM	0*	0
HOWARD HOUSE	N/A	M/A	4,200	12	25
		-	TOTAL	361	14 3
EXISTING INPERVIOUS AREAS			45,7 50 SP		
PROPOSED INPERVI	COUS AREAS: DHAL BUILDING COVER	LACE .	13,900 SF		
ADDITIONAL PAVING COVERAGE			12.790 SF		
TOTAL 1	IMPERVIOUS COVERAGE	-	72,350 SF 4 OF B-2 AR		

NOTE: ATRILLA 16 NOT INCLUDED FOR PARKING CALCULATIONS.



VICINITY MAP

AS BUILT CERTIFICATE

STAMPED CONC, MON. EAST BOOSE RT. 27 100' NORTH OF ROXEURY ROAD

STAMPED CONC. WON. 16.8' WEST OF WEST EDGE OF RT. O'T 0.5 MILES SOUTH OF ROXBURY RD.

APPROVED : FOR PRIVATE WATER AND PRIVATE SEWERAGE SYSTEMS, HOWARD COUNTY HEALTH DEPARTMENT APPROVED : HOWARD COUNTY DEPARTMENT OF PLANNING AND ZONING. CHIEF. DIVISION OF LAND DEVELOPMENT APPROVED : FOR STORM DRAINAGE SYSTEMS AND PUBLIC DATE CHIEF, BUREAU OF ENGINEERING DATE NO. REVISION OWNER / DEVELOPER STEPHEN T. WALKER c/o TRUSTED INFORMATION SYSTEMS 3060 WASHINGTON ROAD, ROUTE 97 GLENWOOD, MARYLAND 21738

> **PROJECT** TRUSTED INFORMATION SYSTEMS AN OFFICE BUILDING ADDITION


TAX MAP 14 ZONED B-2 PARCEL A-2 4th ELECTION DISTRICT

HOWARD COUNTY, MARYLAND

TITLE SHEET

TITLE

Planners • Engineers • Surveyors 3618 Centre Park Drive • Suite 200 • Columbia, MD 21045 410-997-8900 FAX: 410-997-9282 BA-83-31E WP-84-24 F-95-80



DESIGNED BY: C.J.R. DRAWN BY : DAM PROJECT NO: 92209 DATE : WAY 50, 1005 SCALE : AS SHOWN

DRAWING NO. 1 OF II

TYPICAL BUILDING ELEVATION

Pacility shall be inspected annually and after major storms. Inspections should be performed during wet weather to determine if the pond is functioning properly.

of two (2) times a year, once in June and once in September. Other side slopes and maintenance access should be moved as

Visible signs of erosion in the pond as well as ripray outlet area shall be repaired as soon as it is noticed.

Structural components of the pond such as the dam, the riser, and the pipes shall be repaired upon the detection of any damage. The components should be inspected during routine maintenance operations.

Sediment should be removed FROM TOW FORD no later them when the capacity of the pend is half full of sediment, when deemed necessary for seathering reasons, or when deemed necessary by the Boward County's Department of Public Works.

equivaries contained within USDA, SCS "Standards And Specifications For Ponds" (MD-378). The pond remoter) and any beirs, successeur, or assigns shall be responsible for the sofity of the pond and the continued position, surveillance, impostion, and maintenance thereof. The point event(s) shall promptly notify the Soil Conservation District of any usuated observations that may be indications of distress such as excessive seepage,

turbid scopage, sliding or shateping.

OPERATION, MADITENANCE AND INSPECTION

POR BYLLE

ADDRESS CHART STREET ADDRESS 3060 WASHINGTON ROAD TRUSTED INFORMATION SYSTEMS 22 6040 MATER CODE -

50P-95-52

